1. Open the "UpdateVBIOS" folder and execute "UpdateVBIOS.exe" .



2. Press "Y" key when show "update display adapter firmware? ".



```
Administrator: C:\Windows\system32\cmd.exe - update.bat

H:\update VBIOS>update.bat

H:\update VBIOS>devcon.exe update C:\Windows\INF\display.inf PCI\VEN_10DE  & DEV_1617 & SUBSYS_1CED1043
Updating drivers for PCI\VEN_10DE from C:\Windows\INF\display.inf.
Drivers installed successfully.
'DEV_1617' is not recognized as an internal or external command,
operable program or batch file.
'SUBSYS_1CED1043' is not recognized as an internal or external command,
operable program or batch file.

H:\update VBIOS>nvflash.exe 2724_0010_7001__84047B000F-1001816-01.rom

NVIDIA Firmware Update Utility (Version 5.227)
Simplified Version For OEM Only

Checking for matches between display adapter(s) and image(s)...

Adapter: GeForce GTX 980M     (10DE,1617,1043,1CED) H:--:NRM S:00,B:01,PCI,D:00,F:00

Current      - Version:84.04.7B.00.0C ID:10DE:1617:1043:1CED
               GM204 Board (Normal Board)
Replace with - Version:84.04.7B.00.0F ID:10DE:1617:1043:1CED
               GM204 Board (Normal Board)

Update display adapter firmware?
Press 'y' to confirm (any other key to abort):
```

3. Please reboot the system after the program end.
4. Click right bottom on desktop and select "NVIDIA Control panel" after re-enter the system.

5.  Click "System Information" then confirm Video BIOS version: 84.04.7B.00.0F.